



Riello North America

2165 Meadowpine Blvd
Mississauga ON L5N 6H6
Canada

35 Pond Park Road
Hingham, MA 02043
USA

Phone (905) 542-0303
Toll Free (800) 4-RIELLO
Fax (855) 878-6599

40-Series Gas & Oil Training Program

Thank you for your interest in the Riello Residential Training Program. This program is an in-depth technical training on 40-Series gas and oil burners. The 40-Series training is a 1-day course:

1) **40-Series Gas & Oil Training** (1 day course). The course is broken down into oil and gas burners. The Technician(s) will gain a basic understanding and become familiar on how to service and start-up Riello 40-Series burners.

WHO SHOULD ATTEND?

This course is a great tool for **Residential Heating Technicians** as it will help them service and start-up Riello burners with confidence. We will also certify them to service the burners if the trainee completes and passes the course.

COST:

Product Code	Training Course Description	List Price* (NO hotel included)
27019400	Certified Training – 40 Series Gas & Oil 1 day	\$100.00

**Prices do not include applicable taxes*

WHAT IS INCLUDED:

- Training materials
- Lunch/light snacks
- Riello Gear

Course will be confirmed and/or cancelled approximately 4-6 weeks ahead of the course date.

Note regarding payments/invoices; your company will need to be set up in our system – a credit application will need to be completed. Once setup as a customer, a purchase order can be sent for order entry. Invoice to follow, which will include payment details. Information will be provided at a later date. We DO NOT accept credit cards.

Any additional questions or concerns can be sent to: riellotrainingandservice@carrier.com

RIELLO

PLEASE NOTE: Riello *DOES NOT* cover any airfare, hotel, or transportation costs.

Please see below for some information regarding a local hotel and travel.

Please do not book your airfare OR hotel until Riello has confirmed you are in the course.

HOTEL INFORMATION:

Below is a local hotel, which is located approximately 22 miles away from the Boston Airport (BOS) and 2.5 miles from the Riello Hingham office. Please contact the hotel directly to book.

DoubleTree by Hilton Hotel Boston - Rockland

929 Hingham Street

Rockland, MA 02370

Phone: 781-871-0545

Website: <https://www.hilton.com/en/hotels/bosrodt-doubletree-boston-rockland/>

TRANSPORTATION/TRAVEL INFORMATION:

You should fly in and out of **Boston Airport (BOS)**. This airport is approximately 21 miles away from the Riello Hingham office and the local hotel is listed above.

WHAT YOU SHOULD BRING / NEED TO KNOW:

- Safety shoes and work clothes – must be long pants; ***NO open toe shoes, shorts or chewing tobacco.***
- For Canadian trainees, you will need a passport to get through both US and Canadian Customs.
- A credit card for the hotel/transportation.
- Riello is a smoke free facility (inside & outside). There is no smoking allowed on Riello property.
- COVID-19 travel information – listed on next page.

Finalized details will be sent out once the course has been confirmed. The course will be confirmed (and/or cancelled – depending on attendance) approximately 4-6 weeks before the scheduled training dates. Please DO NOT make any travel arrangements until Riello confirms the course is taking place. Riello is not responsible for any airfare/hotel/transportation costs.



IMPORTANT: COVID-19 Travel Information*

It is highly recommended that you review the information that is provided on the United States Government and the Government of Canada websites to ensure that you are aware of all the requirements for entry. Please ensure you also check with your airline to ensure you following any procedures that are required.

<https://travel.gc.ca/travel-covid>

<https://www.usa.gov/covid-passports-and-travel>

*Riello is not responsible for the cost to obtain molecular testing (if required) for travel between Canada and the United States. In the event that an attendee receives a positive test result in Canada in preparation for return to the United States, any costs incurred as a result of a positive test (i.e.: additional hotel costs, meals, airline change fees, etc.) will be the responsibility of customer. If any testing is required, Riello is not responsible for transportation to or from the testing location or the cost of the test.



CURRICULUM: FOR 40-SERIES GAS & OIL TRAINING

THURSDAY: 9:00am - 2:00pm – 40-Series Gas & Oil:

Topics covered – OIL (F3-F20):

- Burner installation and setup
- Sequence of operation
- Burner servicing
- Electrical system
- Oil pump breakdown

Topics covered – GAS (G120-G400):

- Burner installation and setup
- Sequence of operation
- Burner servicing
- Electrical system